

Bauman Machine Inc.

Machine Guarding

Hazards to machine operators that can't be designed around should be shielded to protect the operator from injury or death. Guards and decals which identify the danger must be kept in place whenever the machine is operated. Guards or shields removed for maintenance must be properly replaced before use.

Numerous machinist and workers have been permanently maimed or killed because guards were not installed or were improperly used. Repair or replace damaged guards and shields.


Moving parts present the greatest hazard because of the swiftness of their action and unforgiving and relentless motion. Common machine hazards occurring around moving parts include:

PINCH POINTS

Where two parts move together and at least one of them moves in a circle; also called mesh points, run-on points, and entry points (see Figure).

Examples: Belt drives, chain drives, gear drives, and feed rolls.

When shields cannot be provided, operators must avoid contact with hands or clothing in pinch point areas. Never attempt to service or unclog a machine while it is operating or the engine is running.



WRAP POINTS

Any exposed component that rotates (see Figure).

Examples: Rotating shafts, chucks, drill pipe, such as a PTO shaft or shafts that protrude beyond bearings or sprockets.




Watch components on rotating shafts, such as couplers, universal joints, keys, keyways, pins, or other fastening devices. Splined, square, and hexagon-shaped shafts are usually more dangerous than round shafts because the edges tend to grab fingers or clothing more easily than a round shaft, but round shafts may not be smooth and can also grab quickly. Once a finger, thread, article of clothing, or hair is caught it begins to wrap; pulling only causes the wrap to become tighter.

SHEAR POINTS

Where the edges of two moving parts move across one another or where a single sharp part moves with enough speed or force to cut soft material (see Figure).

Examples: Presses, saws, tailstocks, hydraulic racks.

Remember that crop cutting devices cannot be totally guarded to keep hands and feet out and still perform their intended function. Recognize the potential hazards of cutting and shear points on implements and equipment that are not designed to cut or shear. Guarding may not be feasible for these hazards.




CRUSH POINTS

Points between two objects moving toward each other or one object moving toward a stationary object (see Figure).

Examples: Gears on machines, waycovers, hoist,.

Guard yourself! Never stand between two objects moving toward one another. Make certain the driver knows where the helper is at all times when hitching a tractor to an implement. Do not move between the two objects to complete the hitching until the backing vehicle is completely stopped and the brake is set. Never stand between the tires of an articulating four-wheel drive tractor. Use adequate blocking or lock-out devices when working under equipment.




PULL-IN POINTS

Points where objects are pulled into equipment, usually for some type of processing (see Figure).

Examples: Feed rolls, grinders, and forage harvesters.

Machines are faster and stronger than people. Never attempt to hand-feed materials into moving feed rollers. Always stop the equipment before attempting to remove an item that has plugged a roller or that has become wrapped around a rotating shaft. Remember that guards cannot be provided for all situations--equipment must be able to function in the capacity for which it is designed.



Freewheeling parts, rotating or moving parts that continue to move after the power is shut off are particularly dangerous because time delays are necessary before service can begin.

Allow sufficient time for freewheeling parts to stop moving. Stay alert! Listen and Watch for Motion!

THROWN OBJECTS

Any object that can become airborne because of moving parts (see Figure).

Examples: Rocks, stones, sticks, and pieces of chopped or cut crops.

Keep shields in place to reduce the potential for thrown objects. Wear protective gear such as goggles to reduce the risk of personal injury if you cannot prevent particles from being thrown.



Michigan Occupational Safety and Health Administration (MIOSHA) standards require the following for all farm equipment operated by employees:

Tractors must have a master shield over the PTO drive. Connected equipment must have a tube or tunnel guard over the PTO shaft. Safety decals must be on equipment and must be clearly visible.

All guards, shields or access doors must be in place when equipment is operating.

A warning decal must be placed on an access door when removal of the door would expose the operator to a component that rotates after power is shut off ("freewheeling").

Electrically powered equipment must have a lock-out control on the switch or an electrical switch, mechanical clutch or other positive shut-off device mounted directly on the equipment (such as a silo unloaders, bottom unloading grain bin, or other remote equipment).

Circuit interruption devices on an electric motor, such as circuit breakers or overload protection, must require manual reset to restart the motor. Exceptions include bulk milk coolers, water pumps, or other operations where manual resets would be unduly burdensome. Employees must receive instruction on safe operation and servicing of all field machinery or farmstead equipment with which they are involved. Give instruction at the time of the first assignment to work on each machine and at least once a year thereafter.